



Southeast Management Services, LLC
 240 Fast Lane
 Frisco City AL 36445
 (251) 282-0958,
 Semsfire@gmail.com

Estimate

| | |
|-------------------|------------|
| ESTIMATE # | 1030546499 |
| DATE | 10/30/2023 |
| PO # | |

| CUSTOMER |
|--|
| ASHLAND FIRE DEPARTMENT--ASHLAND, AL, CLAY COUNTY JAMES LEE 21 3RD AVENUE SOUTH ASHLAND, AL, 36251 (334) 338-2260 southernlogger@icloud.com |

| SERVICE LOCATION |
|--|
| ASHLAND FIRE DEPARTMENT--ASHLAND, AL, CLAY COUNTY STATION 21 3RD AVENUE SOUTH ASHLAND, AL, 36251 (334) 338-2260 southernlogger@icloud.com |

| DESCRIPTION | |
|--|--|
| Found passenger cab lift cylinder seal blown out. Per Chief removed for rebuild. Moved work to new R.O. Cylinder in for repair. Need 2.0 Akron kit. | |

Estimate

| Description | Qty | Rate | Tax | Total |
|--|------------|-------------|------------|--------------|
| APPARATUS SERVICE LABOR ENGINE 3: APPARATUS SERVICE LABOR HOURS TO REBUILD 2 INCH AKRON VALVE, AND REINSTALL CAB LIFT CYLINDER. | 6.00 | \$115.00 | \$0.00 | \$690.00 |
| 2INCH-VALVE-KIT ENGINE 3: 2" AKRON SWING OUT VALVE REPAIR KIT. | 1.00 | \$169.45 | \$0.00 | \$169.45 |
| PARTS ENGINE 3: REBUILT CAB CYLINDER LIFT. | 1.00 | \$333.72 | \$0.00 | \$333.72 |
| TRAVEL FEE TRAVEL SURCHARGE. | 1.00 | \$275.00 | \$0.00 | \$275.00 |

| |
|---------------------------|
| PRE-WORK SIGNATURE |
| |
| CUSTOMER MESSAGE |
| |

Estimate Total:

\$1,468.17